# General Environmental Incident Summary

Incident: 3944 Date/Time Notice: 10/21/2015 1520 DEM Incident No:

Responsible Party: Boots Smith Oilfield Services

Date Incident:10/21/2015Time Incident:1400Duration:County:WilliamsTwp:157Rng:95Sec:24Qtr:Lat:48.40305Long:-102.89970Method:Interpolation from map

Location Description: Pipeline Right-of-Way (ROW)

Submitted By: Alex Beach Affiliation:

Address: 3015 16th Street SW, Suite

City: Minot State: ND Zip:

Received By:

Contact Person: Dwight Brasseaux

2501 Airport Drive

Laurel, MS

Distance Nearest Occupied Building: 1000 Feet Release Contained: No

Type of Incident: Water

Description of Released Contaminant: water - from Ames Water Depot (located near HWY 1804)

Volume Spilled: 1.00 barrels Ag Related: No

EPA Extremely Hazardous Substance: Unknown Reported to NRC: Unknown

Cause of Incident:

Approximately 1 bbl of water was released during the process of horizontal drill installation of a pipeline

#### Risk Evaluation:

There were no injuries or evacuations that occurred as a result of this incident.

# of Fatalities: 0 # of Injuries: Affected Medium: 03 - soil

### Potential Environmental Impacts:

With the information available at this time, the likelihood of potential environmental impacts is low.

#### Action Taken or Planned:

The released water will be managed by the responsible party.

Wastes Disposal Location: At this time, the need for disposable has not been determined

Agencies Involved:

## **Updates**

Date: 10/21/2015 Status: Reviewed - Follow-up Required Author: Suess, Bill

**Updated Volume:** 

Notes:

Followup is needed.

Date: 1/22/2016 Status: Inspection Author: Stockdill, Scott

**Updated Volume:** 

Notes:

Arrived on location 1/21/2016.

No sign of impacts at the time of inspection. Contact company and request sample results from the water that was spilled.

More followup is necessary.